

SPEEDIO W1000Xd1

Wide Travel Compact Machining Center



Cutting Out the Waste

Times are changing. Are you ready?

You need a machine that's fast and compact.

With the ability to make any cut.

In this world, only the strong survive.

Make it better with SPEEDIO.





Provides better solutions that eliminate all possible waste, utilizing unparalleled wide travels and maximized high-speed control

In response to customers' expectations of "machining larger workpieces with #30 machine,"
500 mm travel Y-axis has been achieved despite the compact body, breaking common conceptions of #30 machines.


1. NC operability	Equipped with a new usability-oriented "CNC-D00 controller"
2. Machining area	Wide machining area to accommodate a variety of machining,
	such as large workpiece machining and multi-part machining.
3. Productivity	Further improves productivity with optimal operation control
	achieved through machine/controller integrated development
4. Machining capability	Demonstrates a broad range of machining capabilities,
	from high-speed, highly efficient machining to heavy-duty machinin
5. Environmental performance	Creates an earth-friendly plant environment


by greatly reducing power consumption

Basic specifications	
Max. spindle speed (min ⁻¹)	10,000
	Optional: 10,000 high-torque, 16,000
Travels (mm)	X1,000 Y500 Z300
Tool storage capacity (pcs.)	14/21
Rapid traverse rate (m/min)	X/Y/Z 50/50/56
Required floor space (mm)	2,410 x 2,443
BT dual contact spindle	Optional
Coolant Through Spindle	Optional

The large machining area can respond to customers' expectations in a variety of situations, while maintaining high-speed and easy-to-handle features of #30 machining centers.

This new machine enables workpiece machining previously considered impossible in various industries, including the automobile industry.





Equipped with new "CNC-D00 controller" Enhanced usability with 15-inch LCD touch panel

Intuitive operation is possible with new support apps and vertical touch panel screen.

Relevant functions are grouped according to purpose, such as setup and machining, leading to efficient operation.

Production and operation states are visualized, allowing faster understanding.

The new NC controller further improves work efficiency in pursuit of higher productivity.

Home screen

Created a new home screen that serves as the start point of all operations.

Useful information like workpiece counter and tool life are displayed during mass production. New support app screens or conventional screens are opened from here.



Support apps

Created new support apps with improved operability and visibility, such as an ATC tool app that enables all tool settings to be performed on one screen and a production result app that visualizes production results and operation state.



ATC tool app

Machining support

Equipped with functions to reduce the cycle time, such as a machining load waveform display/saving function and an app that enables operators to adjust parameters easily according to machining details.




Waveform display ap

Network function compatible with peripheral equipment/automation

Standard equipped with a PLC function. Increased program memory and object memory enhance peripheral device operation.

Large volumes of program data can be transferred at high speed via Ethernet. The production result app screen can be viewed from the PC's browser.





Maintenance functions

Equipped with functions to improve the operating rate, such as tool monitoring, maintenance time notice, details display when an alarm occurs, and guidance for recovery/check work.



Recovery support app

Accessories

Equipped with handy tools to support smooth operation, such as a calculator where results can be copied/pasted, memo pad you can write in directly on the screen, and file viewer you can use to refer to pdf files.



Calculator





Achieved unprecedented large machining area to accommodate a variety of machining from small to large workpieces

The wide machining area can accommodate constantly varying onsite needs, such as large workpiece machining, long-hour multi-part machining of small parts, multi-product small-volume production with various jigs placed side by side, which enhances the plantwide flexibility.

Ample travels and table size

Ample X/Y-axes travels and sufficient loading capacity allow machining large workpieces and mounting a large jig, not available on conventional #30 machines.


Travels
X 1,000 Y 500
Work area size
X 1,100 Y 500
Max. loading capacity
400 kg

X 1,000mm

Y 500mm

Depth
500mm

A trunnion jig with a turning diameter of 540 mm can be mounted. (High column 250 mm)



Flexibly applicable to various types of machining

Making use of the width and depth of the broad jig area, jigs and workpieces can now be placed freely, enabling more flexible and efficient machining in various processes.

Large workpiece machining




Rotary table and flat jig



Multi-part machining



Parallel arrangement of vises




Improved workability

Linked double doors are used.

The wide opening and highly accessible table improve workability.

Door opening dimension: 1,140 mm



From front to table: 226 mm





Demonstrates high productivity utilizing lightweight and low inertia features of #30 machines and original NC controller

High speed, high acceleration, and high responsiveness have been the aim of machine/controller integrated development, and any wasted motion and time has been thoroughly eliminated to drive machine performance to the fullest and achieve high productivity.

Productivity improvement

Productivity has been further improved by optimally controlling operation with the new CNC-D00 controller and using a low inertia motor.

Program mainly consisting of drilling and tapping Approx. 60% less Or more (compared to previous model) Program mainly consisting of milling and end milling Approx. 30% less

W1000Xd1

General M/C

Simultaneous operation control

Reduction in non-cutting time has been achieved by simultaneously performing tool change and positioning X/Y and additional axes.

General M/C

W1000Xd1



Non-stop ATC


Tool change time has been reduced by increasing the speed of spindle start/stop, Z-axis up/down, and magazine operation.



Rotary table T-200Ad (optional)

Contributes to further improve productivity in multi-face machining. Use of the roller gear cam mechanism achieves high productivity, high accuracy, and extended service life.





0 to 180-deg. indexing time
Clamp mode
1.02s

Unclamp mode **0.45s**



^{*} Data taken running machining program created by Brother

Provides broad cutting performance from high-speed and highly efficient machining to heavy-duty machining

High rigidity based on a special design and use of a high-torque spindle motor achieve stable machining while demonstrating high machining capability.

Max. tool weight 4 kg

Increased the weight of tools that can be mounted.

Combined with wide travels (X 1,000 mm, Y 500 mm), the machine is suitable for a wider variety of applications than ever.

* Changing parameter settings is required. (Tool indexing time is changed.)

Compatible with 7 MPa high-pressure CTS (optional)

The machine is compatible with 7 MPa high-pressure CTS in addition to 1.5 MPa CTS. Demonstrates its abilities in high-speed drilling or peck drilling.

* CTS: Coolant Through Spindle




ø6 × 170mm (L/D=28) Workpiece: Carbon steel

High-power spindle motor

A spindle motor with high torque in the medium- and high-speed range is used to achieve high-speed and highly efficient machining.

The machine with high-torque spec. (optional) greatly improves the torque in the low-speed range, and demonstrates its abilities in heavy-duty steel machining.

Motor torque characteristics



Spindle motor torque values

High-torque spec. (optional)				
Max. torque	92Nm			
Max. output	26.2 kW			


Standard spec.

Max. torque 40Nm

Max. output 18.9kW

Highly rigid structure

Structural parts, such as the base, column, and table, have been specially designed through CAE analysis to secure high rigidity.



Machining examples

End milling (groove)

Cutting amount: 430 cc / Workpiece: Carbon steel ${\it o}$ 16 end mill * High-torque spec.



Large hole machining Hole size: ø50 mm / Workpiece: Carbon steel

Throw-away drill * High-torque spec.

Facing

Depth of cut: ap 3 mm / Workpiece: Carbon steel ø80 face mill * High-torque spec.



Taper tapping

Tapered tap for tubes: PT 1/2 Workpiece: Stainless steel * High-torque spec






Reliability maintains high productivity Earth-friendly machine

Reliability functions that prevent defective products and maintenance functions that prevent machine failure achieve high reliability and maintain high productivity. Our efforts to improve environmental performance and effects of high productivity greatly reduce power consumption, making the machine earth-friendly.

High reliability – Improved chip control

Clean coolant is returned to a clean tank through a tank with a cyclone filter that removes fine chips. This reduces the filter change frequency and extends the service life of the pump.


Tank with cyclone filter (special option for CTS)



High environmental performance

In addition to the low inertia spindle and highly efficient spindle motor, various energy/air saving technologies are utilized to achieve low power consumption. The amount of power consumption can be viewed on the monitor.

Power consumption for one cycle



* Data taken running machining program created

Energy-saving technologies

Low inertia spindle, highly efficient spindle motor, power regeneration system, energy-saving pump, energy-saving NC

Air-saving technologies

Optimized air blast timing, extremely airtight air purge structure

Power consumption app



Reliability/maintenance functions that prevent defective products and machine failure, and assist quick recovery

To maintain productivity at plants, the machine is equipped with many functions that can prevent possible defects in daily production sites, such as tool abrasion, omission of tool attachment, and re-machining of the same workpiece, and that assist with recovery in the case of machine failure or other problems.

ATC tool monitoring

The presence of a spindle tool is detected before and after tool change without using



Machining load monitoring

Machining load applied to the spindle is monitored to issue an alarm when the load is not within the preset range.



Maintenance notice

Notifies operators of maintenance related issues in advance, such as greasing time.

Spaint	-		Service.	-	100.0	8
STATE OF		9000	Hill	369	Service.	4
Part State States		Not*	100	200	Militar	i i
e of the draph.		Serie-	109	200	Willer.	8
	9		276	-)	Not the last	ž.
1						
to .					=14	
-					- 3.	П
-					-	B
100					274	
			1			贸
	_		_	_	100	Ŧ.
					-	

Alarm log

Displays alarm log details to help identify







W1000Xd1 Option



Coolant tank A large 200L tank is available.



Coolant Through Spindle (CTS) Can be selected from 1.5 MPa or 7 MPa Particularly effective in non-step peck drilling.



Column coolant nozzle Powerfully removes chips on and around the workpiece to prevent chips building up



Head coolant nozzle Coolant can reliably be applied to the machining section as the tool and nozzles are set in place.



Signal light, 1, 2, or 3 lamps LED lamps are used. No maintenance required. Can be tilted to improve visibility.



Automatic oil lubricator Regularly applies oil to all lubricating points on the tree axes



Automatic grease lubricator Regularly applies grease to all lubricating points on the three axes *Manual greasing is required for the standard specification model.





switch panel 10 holes A motor-driven door is used, achieving smooth operation.



Chip shower

Chip shower pipes are located at the upper section inside the machine for more efficient flow, and flexible shower nozzles can be directed to the side of the machine cover or sections where chips tend to accumulate





Tool washing, air-assisted type High discharge pressure and flow rate efficiently remove chips attached to the holder. Equipped with a filter cloq warning

function.



Fixture shower valve unit Consists of jig washing valves and pipes to the ceiling of the machine. Pipes from the machine to the required location must be prepared by customers.



Cleaning gun Helps clean the workpiece or chips inside the machine after machining.



Side cover with transparent window (single side, both sides) External light is drawn in to make the inside

of the machine brighter and improve



Work light (right side, left side) LED lamps are used to extend lamp life and save energy.



Optical area sensors are used. Attach area

sensors to prevent operators being caught

Area sensor

in the automatic door.

Spindle override Spindle speed can be changed without changing the program



Manual pulse generator with

A cable is provided for the manual pulse

* Emergency stop with enable switch

generator, making setup easier.

enable switch

Various switches, such as automatic door open/close switches, are set in specific locations. The switch panel (8 holes) is also available so that the position of the manual pulse connector can be changed.



Rotary table T-200Ad

Reduction in the body width secures a

mechanism achieves high productivity.

high accuracy, and extended service life.

wider jig area. Use of the roller gear cam

Master on circuit and switch can be attached. * A switch panel (8 holes, 10 holes) is required separately.



is available.

RS232C 25pin connector

to the side of the control box.

RS232C 25pin connector can be attached

High column 150mm, 250mm, or 350mm

150mm, 250mm and 350mm high columns are available to meet customer's needs.

Coolant tank

1) Coolant tank 200L 2) Coolant tank 200L for CTS 1.5MPa with cyclone filter

- Coolant Through Spindle (CTS) 1.5MPa
- Coolant Through Spindle (CTS) 7MPa
- Column coolant nozzle
- Head coolant nozzle Chin shower
- Tool washing, air-assisted type
- Fixture shower valve unit
- Cleaning gun
- Mesh basket for collecting chips
- High column, 150mm, 250mm, or 350mm

Top cover

provided.

(single side, both sides)

Shutting the opening on the top prevents coolant or chips splashing outside of the

machine. A hole for the mist collector is

- Work light, 1 lamp for right side Work light, 1 lamp for left side
- Signal light, 1, 2, or 3 lamps
- Automatic oil lubricator
- Automatic grease lubricator Automatic door with switch panel 10 holes
- Area sensor
- Manual pulse generator with enable switch
- Connector and hook, for manual pulse generator
- with enable switch Rotary table T-200Ad

- Side cover with transparent window
 - Switch panel 8 or 10 holes
 - Grip cover for tool magazine Data protection switch, key type

Spindle override


visibility

Master on circuit

Tool breakage detector, touch type

Additional axis cable for 1 axes

- RS232C 25pin connector at control box
- 100V outlet in control box
- Power supply expansion 50A
- Parts name sticker set Specified color
- Transformer box Origin alignment mark
- EXIO board assembly
- EXIO board, input32/output32, additional #1 EXIO board, input32/output32, additional #2
- PLC programming software for Windows® 8.1 and 10
- PLC manual
- Industrial network
- 1) CC-Link, master station 2) CC-I ink intelligent device station
- 3) PROFIBUS DP, slave
- 4) DeviceNet, slave 5) PROFINET, slave (scheduled to be installed)
- 6) EtherNet/IP, slave (scheduled to be installed)
- Memory expansion 3Gbytes




- * Depending on the type of coolant, it may have a significant influence on the machine lifecycle. It is recommended to use the coolant which is commercially designated as high lubricity, for example Emulsion type. Especially, the coolant of chemical solution type (ex. Synthetic type) is prohibited to use, because it may cause machine damages.
- * When using CTS (Coolant Through Spindle) function, usage of the coolant of combustible type (ex. Oil-based type) is prohibited.
- * Windows® is a trademark or registered trademark of Microsoft Corporation in the United States and/or other countries.

- Please read the instruction manuals and safety manuals before using Brother products for your own safety. When using oil-based coolant oil or when machining the materials which can cause a fire (ex. Magnesium, resin material), customers are requested to take thoroughgoing safety measures against fire. Depending on the types of cutting material, cutting tools, coolant oil, lubrication oil, it may have an influence on the machine lifecycle. Further questions, please contact our sales representative in charge.
- Leave 700 mm between machines as a maintenance space
- When exporting our machine together with additional 1-axis rotary table or compound rotary table (including case that a rotary table is scheduled to be installed overseas), the machine is deemed to be included. in the "applicable listed items" controlled by the Foreign Exchange and Foreign Trade Law of Japan. When exporting the machine, please obtain required permissions, including an export license, from the Ministry of Economy, Trade and Industry (METI) or Regional Bureaus of Economy, Trade and Industry before shipment. When re-selling or re-exporting the machine, you may need to obtain permissions from METI, and the government of the country where the machine is installed.
- When exporting our machine together with compound rotary table (including case that a rotary table is scheduled to be installed overseas), as a machine conforming to Row 2 of Appended Table 1 of Export Trade Control Order, a relocation detection device is installed on the machine depending on the destination country. After relocating the machine with the detection device, the machine is locked and any operation is temporarily impossible. Please inform your local distributor of machine relocation in advance and apply to perform the release operation of relocated machine.
- In order to operate our machine with an additional axis rotary table installed separately overseas after exporting the machine, the procedure to activate the axis of rotary table is needed. Please inform your local distributor of these processes in advance, because the predetermined procedure is required to perform the activation, In addition, for export to some countries and regions other than "Group A countries", it is not possible to install a compound rotary table separately overseas after exporting the machine. Please make sure to obtain the export license of the machine together with compound rotary table before shipment.

16 17

External Dimensions



Secure 700 mm(27.6 inch) between machines as maintenance space

NC unit specifications

CNC model	CNC-D00			
Control axes	5 axes (X,Y,Z, two additional axes)			
Simultaneously	Positioning	5 axes (X,Y,Z,A,B)		
controlled axes	Interpolation	Linear: 4 axes (X,Y,Z one additional axis)		
		Circular: 2 axes		
		Helical/conical: 3 axes (X,Y,Z)		
		Involute interpolation (optional)		
Least input increment	0.001mm, 0.0001inch, 0.001 deg.			
Max.programmable dimension	±999999.999mm, ±99999.9999inch			
Display	15-inch color LCD touch display			
Memory capacity	500 Mbytes (Total capacity of program and data bank)			
External communication	USB memory interface, Ethernet, RS232C (optional)			
No.of registrable programs	4,000 (Total capacity of program and data bank)			
Program format	NC language, conversation (changed by parameter), conversation from conversation program to NC language program available			

^{*} Number of "control axes" and/or "simultaneously controlled axes" are the maximum number of axes, which will differ depending on the destination

Machine Specifications

Item				W1000Xd1 / W1000Xd1 RD *10		
CNC unit		<u> </u>		CNC-D00		
	X axis		mm(inch)	1,000 (39.4)		
Travels	Y axis	xis		500 (19.7)		
	Z axis		mm(inch)	300 (11.8)		
	Distance between tabl	e top and spindle nose end	mm(inch)	180~480 (7.1~18.9)		
Table	Work area size		mm(inch)	1,100 × 500 (43.3 × 19.7)		
	Max. loading capacity	(uniform load)	kg(lbs)	300[400 *1] (661[881*1])		
	Spindle speed		min ⁻¹	10,000min ⁻¹ specifications:1~10,000, 10,000min ⁻¹ high-torque specifications (optional):1~10,000, 16,000min ⁻¹ specifications (optional):1~16,000		
Spindle	Speed during tapping		min ⁻¹	MAX. 6,000		
оришо	Tapered hole			7/24 tapered NO.30		
	BT dual contact spindl	e (BIG-PLUS)		Optional		
	Coolant through spind		MPa	1.5/7.0: Optional		
	Rapid traverse rate (X)		m/min(inch/min)	50 × 50 × 56 (1,969 × 1,969 × 2,205)		
Feed rate	Cutting feed rate		mm/min(inch/min)	X,Y,Z:1~30,000 (0.04 ~ 1,181) *2		
	Tool shank type			MAS-BT30		
	Pull stud type *3			MAS-P30T-2		
	Tool storage capacity		pcs.	14 / 21		
ATC unit	Max. tool length		mm(inch)	250 (9.8)		
	Max. tool diameter		mm(inch)	ø110 (4.3)		
	Max. tool weight *4		kg(lbs)	3.0(6.6) [4.0(8.8) *5]/tool, (TOTAL TOOL WEIGHT: 25 (55.1) for 14 tools, 35 (77.2) for 21 tools)		
	Tool selection method			Random shortcut method		
Facilishana 45 40	Tool To Tool		sec	0.6		
Tool change time *6	Chip To Chip		sec	1.2		
Electric motor	Main spindle motor (10min/continuous) *7		kW	10,000min ⁻¹ specifications: 10.0/6.9, 10,000min ⁻¹ high-torque specifications (optional): 12.8/9.2, 16,000min ⁻¹ specifications (optional): 7.3/5.0		
	Axis feed motor		kW	X,Y axis: 1.0 Z axis: 2.0		
	Power supply			AC200V±10%、50/60Hz±1Hz		
	Power capacity (continuous)			10,000min ⁻¹ specifications: 9.5, 10,000min ⁻¹ high-torque specifications (optional): 10.4,		
Power source			kVA	16,000min ⁻¹ specifications (optional): 9.5		
		Regular air pressure	MPa	0.4~0.6(recommended value 0.5MPa) *8		
	Air supply	Required flow	L/min	45		
	Height		mm(inch)	2,553 (100.5)		
Machining dimensions	Required floor space [with control unit door open]		mm(inch)	2,410×2,443 [3,072] (94.9×96.2[121.0])		
-			kg(lbs)	3,350 (7,386)		
		nal axis positioning (ISO230-2:1988)	mm(inch)	0.006 ~ 0.020 (0.00024 ~ 0.00079)		
Accuracy *9			mm(inch)	Less than 0.004 (0.00016)		
Front door			, , ,	2doors		
Standard accessories	Instruction Manual (D)	/D 1 set), leveling bolts (4 pcs.), leveling pla	ate (4 ncs)			

^{*1} Acceleration must be adjusted for X and Y axes. *2 When using high accuracy mode B. *3 Brother specifications apply to the pull studs for CTS. *4 Actual tool weight differs depending on the configuration and center of gravity. The figures shown here are for reference only. *5 Parameter settings must be changed. (Tool magazine indexing time will change.) *6 Measured in compliance with JIS B6336-9 and MAS011-1987. *7 Spindle motor output differs depending on the spindle speed. *8 Regular air pressure varies depending on the machine specifications, machining program details, or use of peripheral equipment. Set the pressure higher than the recommended value. *9 Measured in compliance with ISO standards and Brother standards. Please contact your local distributor for details. *10 The machine needs to be equipped with a relocation detection device depending on the destination. Machines equipped with a relocation detection device come with "RD" at the end of the model name.

NC functions

Standard NC functions				Op	tional NC functions
Absolute / incremental Inch / metric Coordinate system setting Corner C / Corner R Rotational transformation Synchronized tap Subprogram High-accuracy mode A III High-accuracy mode B I (look-ahead 160blocks) Tool life / Spare tool Automatic workpiece measurement *1 Dry run Machine lock Restart Rapid traverse override Cutting feed override	Background editing Graphic display Screen shot File viewer Status log Alarm log Operation log Production performance display Computer remote Auto notification OPC UA Built-in PLC External input signal key Automatic power off Servomotor off standby mode Automatic conlant off	NC	Menu programming Local coordinate system Expanded workpiece coordinate system One-way positioning Inverse time feed Programmable data input Tool length compensation Cutter compensation Scaling Mirror image External sub program call Multiple skip function Macro Operation in tape mode	Spino High	ory expansion 3Gbytes Ile override accuracy mode BII, -ahead 1,000 blocks, with smooth path of Submicron command *2 Interrupt type macro Rotary fixture offset Involute interpolation
Cutting feed override Tool length measurement Spindle load monitoring ATC monitoring Adjust machining parameter screen Check over load Waveform display / waveform output to memory card Heat expansion compensation system II (X,Y,Z axes) Tax return function	Automatic coolant off Automatic work light off Chip shower off delay Power consumption display Motor insulation resistance measurement Tool washing filter with filter clogging detection Operation level Backlash compensation	Conversation	n Operation program Schedule program Automatic tool selection Automatic cutting condition setting Automatic tool length compensation setting Automatic cutter compensation setting Automatic calculation of unknown number input	*2. V t * Fur ava	Measuring instrument needs to be prepare y users. When the submicron command is used,ch o the conversation program is disabled. nctions listed under (NC) and (Conversational allable only for NC programs and conversa-

- ation) are

country and the machine specifications.

* Ethernet is a trademark or registered trademark of XEROX in the United States.

Global Service Sites

Brother Technology Center Chicago

BROTHER INTERNATIONAL CORP.

2200 North Stonington Avenue, Suite 270, Hoffman Estates, IL 60169, U.S.A. PHONE:(1)224-653-8415 FAX:(1)224-653-8821

Brother Technology Center Frankfurt

BROTHER INTERNATIONALE INDUSTRIEMASCHINEN GmbH Hoechster Str.94, 65835 Liederbach, Germany PHONE:(49)69-977-6708-0 FAX:(49)69-977-6708-80

Brother Technology Center Bengaluru

BROTHER INTERNATIONAL (INDIA) PVT LTD.

SB-111-112, 1st Stage, 2nd Cross, Peenya Indl Estate, Bengaluru - 560058 Karnataka, India PHONE:(91)80-43721645

Brother Technology Center Shanghai

BROTHER MACHINERY (SHANGHAI) LTD.

Unit 01, 5/F., No.799, West Tianshan Rd., ChangNing District Shanghai 200335, P.R.China PHONE:(86)21-2225-6666 FAX:(86)21-2225-6688

Brother Technology Center Chongqing

BROTHER MACHINERY (SHANGHAI) LTD.

Room 30, 31, NO.104 Cuibai Road, Dadukou District, Chongqing Province, 400084, P.R.China PHONE:(86)23-6865-5600 FAX:(86)23-6865-5560

Nangjing Office

BROTHER MACHINERY (SHANGHAI) LTD.

 $503\ Room, Building\ No.1, No.39, Dongcun\ Road, Jiangning\ District, Nangjing\ City,\ Jiangsu\ Province, P.R. China\ PHONE: (86) 25-87185503$

Brother Technology Center Queretaro

BROTHER INTERNATIONAL DE MÉXICO, S.A. DE C.V.

Calle 1 No.310 Int 15, Zona Industrial Jurica, Parque Industrial Jurica,

Queretaro, QRO C.P. 76100 México

PHONE:(52)55-8503-8760 FAX:(52)442-483-2667

Brother Technology Center Bangkok

BROTHER COMMERCIAL (THAILAND) LTD.

317 Pattanakarn Road, Pravet Sub-District, Pravet District, Bangkok 10250, Thailand PHONE:(66)2321-5910 FAX:(66)2321-5913

Gurugram Service Center

BROTHER INTERNATIONAL (INDIA) PVT LTD.

CE SERVICED OFFICES PVT. LTD., DLF CYBER HUB, Building No 10, Tower A, Level 1, Phase 3, DLF Cyber City, Gurugram - 122002 Haryana - India PHONE:(91)80-43721645

Brother Technology Center Dongguan

BROTHER MACHINERY (SHANGHAI) LTD.

1F, Fuyuan Business Center Building, No.5 Lane 13, Maiyuan Road, Xin'an community, Chang'an Town, Dongguan City, Guangdong Province, 523008, P.R.China PHONE:(86)769-2238-1505 FAX:(86)769-2238-1506

Ningbo Office

BROTHER MACHINERY (SHANGHAI) LTD.

1005-2 Room,Block C,Hebang building. No 899,Tiantong north road.Ningbo City, Zhejiang Province,P.R.China

PHONE:(86)574-88139798 FAX:(86)57-88139792

Figures in brackets () are the country codes.

Specifications may be subject to change without any notice.

BROTHER INDUSTRIES, LTD.

Machinery Business Division

1-5, Kitajizoyama, Noda-cho, Kariya-shi, Aichi-ken 448-0803, Japan https://www.brother.co.jp

